## **Turner**

Turner Construction Company 2001 N. Lamar, Suite 100 Dallas, TX 75202

Phone: (214) 721-8400 Fax: (214) 721-8493

5/17/11

Mr. Bill Burke Collin County 4600 Community Ave. McKinney, TX 75071

RF:

Collin County Courthouse Addition

Owner Project #R0508003.00 Turner Project #1692600

SUBJ: PCO #064 R1 - Existing Dock Repairs.

Dear Mr. Burke:

We have finalized the required quotations for PCO #064 R1 - Existing Dock Repairs.

We have reviewed the scope of work and have verified that all extra work items are in compliance with our contract agreement. Attached is a detailed itemization of the extra costs. Total amount of this request is *Two Thousand Nine Hundred Ninety Four dollars* (2,994).

If you have any questions regarding this Change Order Request, please call me at your earliest convenience. This pricing is valid for (10) days, after which, we reserve the right to re-evaluate.

Please review and acknowledge your approval in the space below. Once approval is achieved, we will expect this PCO to be included in a forthcoming Change Order.

Best Regards,

J. Leos

John Leos

Approved by:

Collin County	Date
PGAL	Date

cc:

Brad Harris & Sara Hoglund- Collin County Brian Nicodemus- PGAL Matt Nail, Kevin Karagias, & Ronnie Holcomb- TCCo

## **Turner**

PCO No.: 064 R1
PCO Title: Existing Dock Work Repairs.

Project: Collin County Courthouse Addition

Project No.: R0508003.00

Туре	Company	Description	Subcontractor Base Price	Subcontractor W/C & GL	Subcontractor Total Price
			A	В	C = A+B
Subcontractor	Potter	Infill Dock Hole with 4 CY of Flowable Fill, Concrete, Dowels, Pump & Labor.	1,308	45	1,353
Notes:  1. Does Not Include Dock Leveler Install. 2. Concrete to be Broom Finish. 3. No Clean Cutting of Existing Concrete is Included.	Remove Bollard at Dock Area, Hydro Hammer Rental, Welder, Removal/Disposal, & Backfill Area.	1,324	45	1,369	
		1			
	Notes:	-			
		The state of the s		-	
	No Clean Cutting of Existing Concrete is Included.				
		To Remove the Bollard 12* Below Grade.     No stain or sealer is Included.			
			-		
			-		
				1	
		Subtotal	2,632	90	2,722

10% OH&P\_\_\_\_\_ Total Cost \$ 272

Notes: